IN THE SPECIFICATION:

Please amend the fourth paragraph on page 6 beginning at line 15 as follows:

The bearings 34 and 38 36 are mounted within a split bearing housings to avoid external leaks, each bearing housing comprised of a lower half 80, 82 welded to the inside of a respective housing side plate 38. A top cap 84, 86 is secured to a respective housing lower half 80, 82 by cap screws 88.